

AGREEMENT FOR THE PERFORMANCE OF COMPACTOR REPAIR WORK

This agreement for the performance of compactor repair work ("Agreement") is made and entered into this 3rd day of October, 2011 ("Effective Date") by and between the City of Redlands, a municipal corporation of the State of California ("City") and Blane's Equipment Repair, Inc. ("Contractor"), a California corporation. City and Contractor are sometimes individually referred to herein as a "Party" and, together, as the "Parties."

In consideration of the mutual promises contained herein, the City of Redlands and Blane's Equipment Repair, Inc. agree as follows:

AGREEMENT

1. Compactor Repair Work. City hereby authorizes Contractor to perform repair work for City's 1987 Caterpillar 826 Compactor (City Vehicle # 892, VIN # 87X00550), hereinafter called the "Compactor." The repair work is more specifically described in Exhibit "A," attached hereto and incorporated herein by reference.

2. Cost. City shall pay Contractor, as total compensation for the repair work, an amount not to exceed Ninety Eight Thousand Nine Hundred Fifty Seven and 38/100 Dollars (\$98,957.38). An invoice shall be sent to City after the Compactor repair work has been performed and the Compactor delivered to City. The invoice will be paid by City within thirty (30) days of receipt.

3. Compactor Delivery. The repair work and delivery of the Compactor to City's Landfill site shall be completed by Contractor within six (6) weeks from Effective Date of this Agreement.

4. Warranty. Contractor hereby warrants the repair work for parts and workmanship for a period of twelve (12) months from the date of City's acceptance of the Compactor. All components of the Compactor shall be dyno tested to ensure the quality of the component before the Compactor is delivered to the City. A field test is required before the Compactor will be deemed acceptable by City.

5. Insurance.

5.1 Contractor's Insurance to be Primary All insurance required by this Agreement shall be maintained by Contractor for the duration of the performance of the repair work and shall be primary with respect to City and non-contributing to any insurance or self-insurance maintained by City. Contractor shall provide City with Certificates of Insurance and endorsements evidencing such insurance prior to commencement of the Services.

5.2 Comprehensive General Liability Insurance. Contractor shall secure and maintain in force throughout the duration of the Agreement comprehensive general liability insurance with carriers acceptable to City. Minimum coverage of one million dollars

(\$1,000,000) per occurrence and two million dollars (\$2,000,000) aggregate for public liability, property damage and personal injury is required. City shall be named as an additional insured and the insurance policy shall include a provision prohibiting cancellation of said policy except upon thirty (30) days prior written notice to City. Such insurance shall be primary and non-contributing to any insurance or self-insurance maintained by City. Certificates of insurance and endorsements shall be delivered to City prior to commencement of the repair work.

5.3 Business Auto Liability Insurance. Contractor shall have business auto liability coverage, with minimum limits of one million (\$1,000,000) per occurrence, combined single limit for bodily injury liability and property damage liability. This coverage shall include all Contractor owned vehicles used on the project, hired and non-owned vehicles, and employee non-cityship vehicles. City shall be named as an additional insured and a certificate of insurance shall be delivered to City prior to commencement of the repair work.

5.4 Hold Harmless and Indemnification. Contractor shall indemnify, hold harmless and defend City and its elected officials, agents, and employees from and against any and all claims, losses or liability, including attorney's fees, arising from injury or death to persons or damage to property occasioned by any act, omission or failure of Contractor, its officer, agents and employees in performing the repair work required by this Agreement.

6. Waiver. Waiver by City of any breach or defect of this Agreement or of any term, covenant or condition herein contained shall not be deemed to be a waiver of any subsequent or other breach of the same or any other term, covenant or condition.

7. Attorneys' Fees and Costs. In the event any action is commenced to enforce or interpret any of the terms or conditions of this Agreement the prevailing Party shall, in addition to costs and any other relief, be entitled to recovery of its reasonable attorneys' fees, including fees for use of in-house counsel by a Party.

8. Notices. Any and all notices or demands shall be in writing. They shall be served either personally or sent by United States mail, and shall be deemed to have been given when personally served or when deposited in the United States mail, certified or registered, with postage prepaid and properly addressed. For the purposes hereof, the addresses of the Parties (until notice of a change thereof given as provided in this Paragraph) shall be as follows:

To City:

City Manager
City of Redlands
35 Cajon Street, Suite 200
P.O. Box 3005 (mailing)
Redlands CA 92373

To Contractor:

Blane's Equipment Repair, Inc.
8637 Hemlock Avenue
Fontana, CA 92335

9. Binding on Successors. This Agreement shall be binding upon and inure to the benefit of the successors-in-interest of the Parties.

10. Time of Essence. Time is of the essence of each provision of this Agreement.

11. Integrated Agreement. This Agreement contains the entire agreement of the Parties with respect to the subject matter hereof, and shall not be amended or modified except by a written agreement approved by the Parties.

CITY OF REDLANDS

BLANE'S EQUIPMENT REPAIR, INC.

By: Pete Aguilar
Pete Aguilar, Mayor

By: Blane Paul

ATTEST:

Sam Irwin
Sam Irwin, City Clerk

BLANE'S EQUIPMENT REPAIR, INC.

8637 Hemlock Avenue, Fontana, CA 92335

Remit To: 34924 BORCHARD ROAD

LAKE ELSINORE, CA 92530

Phone#909-357-8391 Fax#909-829-8525

Amended Quote

Date	Quote #
8/11/2011	881-E3

CITY OF REDLANDS
PO BOX 3005
REDLANDS, CA 92373

		Description	Job #	Eq. or Serial #
		826-C ENGINE	11064	87X550
Qty	Part #	Description	Unit price	Total
1	8C-8711	GASKET KITS		
1	233-7083	CENTRAL & LOWER	52.56	52.56T
1	5P-8053	FRONT STRUCTURE	128.15	128.15T
1	5P-8371	CYLINDER HEAD	272.80	272.80T
1	6V-0851	TURBO INSTALL	72.80	72.80T
1	5P-8329	AIR COMPRESSOR INSTALL	23.96	23.96T
1	141-9792	FUEL SYSTEM	110.88	110.88T
1	232-6574	COOLER AND LINES	112.98	112.98T
1	5P-8059	REAR STRUCTURE	103.80	103.80T
1	128-2922	WATER LINES GP	54.95	54.95T
		WATER PUMP INSTALL	79.10	79.10T
2	4N-1650	HEAD ALIGNMENT DOWELS	6.12	12.24T
6	9F-2247	1/8" PIPE PLUG	1.65	9.90T
7	4W-5492/317-8766	MAIN BEARING	46.21	323.47T
2	7N-8947/253-1752	PLATE THRUST	33.29	66.58T
6	0R-2975	CYLINDER PACK	474.01	2,844.06T
6	9Y-9497/334-2671	ROD BEARING	27.29	163.74T
12	6N-6872/305-6843	LIFTER SPRING	8.62	103.44T
11	4S-6137	EXH STUD	10.69	117.59T
1	7L-0520	EXH STUD LONG	8.46	8.46T
10	2N-2765	EXHAUST BOLT	5.76	57.60T
30	2N-2766	EXHAUST NUT	5.16	154.80T
11	108-3612	EXHAUST SPACER	15.61	171.71T
1	2S-3770	EXHAUST SPACER	11.25	11.25T
12	5M-2894	EXHAUST WASHER	0.34	4.08T
1	0R-3674	CYLINDER HEAD DI PENCIL	1,806.14	1,806.14T
6	6L-7442	FUEL ADAPT STUD	4.43	26.58T
1	3J-5390	HEAD PIPE PLUG	3.00	3.00T
4	3J-5389	HEAD PIPE PLUG	4.25	17.00T
1	8N-8258	BEARING SLEEVE - TIMING GEAR	54.37	54.37T
1	4N-0343/131-7123	BEARING SLEEVE - TIMING GEAR	39.15	39.15T
3	4N-0999/165-6170	RUBBER PLUG IN BLOCK	7.40	22.20T
1	0R-0918	ENGINE OIL PUMP	506.14	506.14T
2	2P-4005/275-2604	ENGINE OIL FILTER (1 before Dyno Test & 1 after Dyno Test)	34.27	68.54T

Quote Approved by:

Subtotal

NOTE: Quote does not include any salvage or reconditioning machine work, any unforeseen, unacceptable Core Charges or Freight Charges. Quote does not include any REMOVAL or INSTALLATION CHARGES unless specified. Warranty is as follows: Twelve (12) months Parts & Workmanship. If a Warranty issue occurs, the Customer's Service records will be requested for inspection. ALL COMPONENTS ARE DYNO TESTED TO ENSURE THE QUALITY OF THE COMPONENT BEFORE BEING RELEASED TO THE CUSTOMER.

Sales Tax (8.75%)**Total**

\$ 34,733.78

BLANE'S EQUIPMENT REPAIR, INC.

8637 Hemlock Avenue, Fontana, CA 92335

Remit To: 34924 BORCHARD ROAD

LAKE ELSINORE, CA 92530

Phone#909-357-8391 Fax#909-829-8525

Amended Quote

Date	Quote #
8/11/2011	881-E3

CITY OF REDLANDS
PO BOX 3005
REDLANDS, CA 92373

		Description	Job #	Eq. or Serial #
		826-C ENGINE	11064	87X550
Qty	Part #	Description	Unit price	Total
1	4N-4668	CRANK CASE BREATHER	61.31	61.31T
2	5P-2230	HOSE CLAMP	3.71	7.42T
1	0R-8217/10R-0482	WATER PUMP	354.99	354.99T
1	3V-3065	COOLANT HOSE ASSEMBLY	41.09	41.09T
1	8N-7140	COOLANT HOSE	29.57	29.57T
1	9N-3367	COOLANT FILTER	28.22	28.22T
1	9N-3711/248-6513	THERMOSTAT	42.22	42.22T
1	0R-5511	REMAN ENGINE OIL COOLER	823.52	823.52T
1	0R-5370	TURBO CHARGER - LATE	1,570.52	1,570.52T
THESE PARTS ARE USED TO CHANGE OUT THE AIR COMPRESSOR				
1	8M-0755	A/C CONNECTOR	3.19	3.19T
1	4N-4935	A/C HOSE	39.39	39.39T
1	1N-4475/1Y-0683	A/C HOSE ASSEMBLY	37.43	37.43T
1	3B-7744	A/C NIPPLE	5.54	5.54T
1	9L-5254	A/C ELBOW	12.29	12.29T
1	2B-0858	A/C PLUG	3.63	3.63T
1	2W-0671	A/C HOSE OIL PRESSURE	29.21	29.21T
1	0R-8172	AIR COMPRESSOR	574.64	574.64T
1	5F-5434	GOVERNOR VENT	1.94	1.94T
1	1P-7125	GOVERNOR ASSEMBLY	47.22	47.22T
3	5P-8245	A/C MOUNT WASHER	0.59	1.77T
THE FOLLOWING PARTS ARE NEEDED FOR THE FUEL SYSTEM				
	LABOR	RECONDITION FUEL INJECTION PUMP	2,900.00	2,900.00
6	4W-7017	PENCIL NOZZLE	157.59	945.54T
1	0R-3379	FUEL TRANSFER PUMP/GEAR DRIVEN	276.67	276.67T
1	105-2508	FUEL PRIMING PUMP	85.39	85.39T
1	4N-5823/1R-0749	FUEL FILTER	20.44	20.44T
1	9L-5120	AIR FUEL HOSE	24.07	24.07T
THE FOLLOWING PARTS ARE FOR REBUILDING THE FAN DRIVE SYSTEM				
1	8N-5827/131-7123	IDLER SHOCK ABSORBER	255.36	255.36T
1	5M-9735	LIP SEAL IDLER	6.09	6.09T
2	6B-1124	BALL BEARING IDLER	20.14	40.28T

Quote Approved by:

Subtotal

NOTE: Quote does not include any salvage or reconditioning machine work, any unforeseen, unacceptable Core Charges or Freight Charges. Quote does not include any REMOVAL or INSTALLATION CHARGES unless specified. Warranty is as follows: Twelve (12) months Parts & Workmanship. If a Warranty issue occurs, the Customer's Service records will be requested for inspection. ALL COMPONENTS ARE DYNO TESTED TO ENSURE THE QUALITY OF THE COMPONENT BEFORE BEING RELEASED TO THE CUSTOMER.

Sales Tax (8.75%)**Total**

BLANE'S EQUIPMENT REPAIR, INC.

8637 Hemlock Avenue, Fontana, CA 92335

Remit To: 34924 BORCHARD ROAD

LAKE ELSINORE, CA 92530

Phone#909-357-8391 Fax#909-829-8525

Amended Quote

Date	Quote #
8/11/2011	881-E3

CITY OF REDLANDS
PO BOX 3005
REDLANDS, CA 92373

		Description	Job #	Eq. or Serial #
		826-C ENGINE	11064	87X550
Qty	Part #	Description	Unit price	Total
1	2S-6151	GASKET IDLER	1.36	1.36T
1	5S-2106	LIP SEAL FAN	9.26	9.26T
1	8H-9789	BALL BEARING FAN	28.95	28.95T
1	3L-1425	BALL BEARING FAN	40.02	40.02T
1	9F-4446	FAN MOUNTING SEAL	4.82	4.82T
1	4N-6302	VEE BELT SET	88.82	88.82T
1	4N-8225	ALT PULLEY	68.24	68.24T
1	6N-0341	ALT BELT	24.47	24.47T
	LABOR	REGROOVE (1) FAN PULLEY (4) GROOVES	232.00	232.00
	LABOR	REGROOVE (1) BELT IDLER PULLEY (3) GROOVES	174.00	174.00
	LABOR	REGROOVE (1) CRANK PULLEY (5) GROOVES	390.00	390.00
1	7N-9785/203-3222	COOLANT SWITCH	55.98	55.98T
13	248-7518	GALLONS 15-40 WT. ENGINE OIL	18.30	237.90T
1	9U-7725	PAINT CAT YL	41.30	41.30T
4	9U-6926	SURFACING DISC 3"	2.92	11.68T
3	6V-0185	SURFACING DISC 5"	4.54	13.62T
1	155-0695/27131	LOCKTITE	32.88	32.88T
5	138-8440/117-4633	CLEANER	18.58	92.90T
1	4C-5300	GASKET SEALANT	57.21	57.21T
	LABOR	POLISH CAMSHAFT	210.00	210.00
	LABOR	POLISH CRANKSHAFT	0.00	0.00
	LABOR	RECONDITION AFTER COOLER - CLEAN AND PRESSURE TEST	0.00	0.00
	LABOR	RECONDITION AND DYNO TEST (1) 826-C ENGINE	7,200.00	7,200.00
		ENVIRONMENTAL CHG	35.00	35.00
		TOTAL \$30,246.84		
		ENGINE AMENDED QUOTE		
1	102-8502/102-8501	MANIFOLD CENTER SECTION	652.53	652.53T
2	101-7352/102-8608	MANIFOLD END SECTION	375.84	751.68T
2	5L-8854	RING SEAL	6.60	13.20T

Quote Approved by:

Subtotal

NOTE: Quote does not include any salvage or reconditioning machine work, any unforeseen, unacceptable Core Charges or Freight Charges. Quote does not include any REMOVAL or INSTALLATION CHARGES unless specified. Warranty is as follows: Twelve (12) months Parts & Workmanship. If a Warranty issue occurs, the Customer's Service records will be requested for inspection. ALL COMPONENTS ARE DYNO TESTED TO ENSURE THE QUALITY OF THE COMPONENT BEFORE BEING RELEASED TO THE CUSTOMER.

Sales Tax (8.75%)**Total**

BLANE'S EQUIPMENT REPAIR, INC.

8637 Hemlock Avenue, Fontana, CA 92335

Remit To: 34924 BORCHARD ROAD

LAKE ELSINORE, CA 92530

Phone#909-357-8391 Fax#909-829-8525

Amended Quote

Date	Quote #
8/11/2011	881-E3

CITY OF REDLANDS
PO BOX 3005
REDLANDS, CA 92373

		Description	Job #	Eq. or Serial #
		826-C ENGINE	11064	87X550
Qty	Part #	Description	Unit price	Total
1	9L-5839	COUPLING	91.97	91.97T
1	6N-9743	SUPPORT	336.91	336.91T
		TIMING ADVANCE		
1	4W-4616	SEAL- QUAD RING	5.40	5.40T
1	4W-0435	SEAL- QUAD RING	7.89	7.89T
1	9X-7715	SEAL- QUAD RING	19.13	19.13T
4	1S-5440	DOWEL	3.56	14.24T
1	4N-2927	RACE- THRUST	3.21	3.21T
2	9N-3666	VALVE- WATER	16.00	32.00T
15	5P-1255	CM HOSE STK	0.62	9.30T
2	2S-2053	CLIP	6.21	12.42T
1	9N-0952	TUBE- BREATHER (BROKEN)	186.11	186.11T
1	6P-8028	BRACKET	13.59	13.59T
1	8N-1667	GAUGE OIL LEVEL	36.16	36.16T
1	4N-1215/223-5814	BODY ASSEMBLE OIL COOLER	113.74	113.74T
2	8T-6765	PLUG PIPE	2.28	4.56T
1	4N-0827	ADAPTER OIL FILTER	194.67	194.67T
1	6S-6308	PIN	0.97	0.97T
1	3B-4617	COTTER PIN	0.07	0.07T
1	4S-5367	BUSHING ASSEMBLY IDLER ARM	44.09	44.09T
1	7N-1210	FRONT MOTOR MOUNT	127.76	127.76T
1	1Y-0413	TEE	19.15	19.15T
1	3B-7744	FITTING	5.54	5.54T
12	6N-8942	BOLT CONN ROD	37.96	455.52T
12	8L-3441	NUT CONN ROD	0.90	10.80T
1	9K-2464	CLIP	8.89	8.89T
1	4W-4774/MP-2383	BACKING PLATE (WATER PUMP)	106.45	106.45T
2	3B-5011	CLIP	0.65	1.30T
6	4P-1396/178-1318	ADAPTER AS.	16.65	99.90T
		INJECTION LINE CLAMPS		
1	141-2674	BRACKET	24.94	24.94T
3	7C-9198	BLOCK	37.03	111.09T
1	141-2672	BRACKET	20.32	20.32T
6	0S-1615	BOLT	0.15	0.90T
6	5P-0537	WASHER	0.23	1.38T

Quote Approved by:

Subtotal

NOTE: Quote does not include any salvage or reconditioning machine work, any unforeseen, unacceptable Core Charges or Freight Charges. Quote does not include any REMOVAL or INSTALLATION CHARGES unless specified. Warranty is as follows: Twelve (12) months Parts & Workmanship. If a Warranty issue occurs, the Customer's Service records will be requested for inspection. ALL COMPONENTS ARE DYNO TESTED TO ENSURE THE QUALITY OF THE COMPONENT BEFORE BEING RELEASED TO THE CUSTOMER.

Sales Tax (8.75%)**Total**

BLANE'S EQUIPMENT REPAIR, INC.

8637 Hemlock Avenue, Fontana, CA 92335

Remit To: 34924 BORCHARD ROAD

LAKE ELSINORE, CA 92530

Phone#909-357-8391 Fax#909-829-8525

Amended Quote

Date	Quote #
8/11/2011	881-E3

CITY OF REDLANDS
PO BOX 3005
REDLANDS, CA 92373

		Description	Job #	Eq. or Serial #
		826-C ENGINE	11064	87X550
Qty	Part #	Description	Unit price	Total
3	1A-9579	BOLT	0.32	0.96T
2	0S-1618	BOLT	0.23	0.46T
8	9M-1974	WASHER	0.24	1.92T
1	054-4984	SPACER	9.48	9.48T
1	141-2675	BRACKET	32.34	32.34T
2	1W-9169	CLAMP FUEL LINES	4.75	9.50T
2	5P-4939	SCREW- MACHINE	1.90	3.80T
7	1W-9168	CLAMP	4.04	28.28T
3	7M-9831	SCREW	0.99	2.97T
6	6V-7699	WASHER	0.18	1.08T
3	4B-2047	NUT	0.09	0.27T
1	1W-9167	CLAMP	9.37	9.37T
1	1W-9168	CLAMP	4.04	4.04T
1	9L-9159	SPACER	2.69	2.69T
8	1W-9168	CLAMP	4.04	32.32T
4	1W-9169	CLAMP	4.75	19.00T
2	7M-9910	SCREW	1.01	2.02T
2	1W-9167	CLAMP	9.37	18.74T
2	4B-4274	WASHER	0.15	0.30T
2	104-3038	SCREW	1.24	2.48T
2	144-3517	CLAMP AS	18.60	37.20T
1	1W-9168	CLAMP	4.04	4.04T
2	4B-2047	NUT	0.09	0.18T
8	6V-7699	WASHER	0.18	1.44T
1	7M-9831	SCREW	0.99	0.99T
2	4B-2047	NUT	0.09	0.18T
1	7N-9785/203-3222	SENSOR COOLANT TEMP (EMS)	55.98	55.98T
1	8T-8730	SOCKET CONNECT - OIL PRESSURE SENDING UNIT	1.08	1.08T
1	107-0611	SWITCH ASSEMBLY - OIL PRESSURE SENDING UNIT	55.84	55.84T
1	155-2270	PLUG KIT- OIL PRESSURE SENDING UNIT	4.08	4.08T
1	6N-5926	SENDING UNIT TEMP	29.35	29.35T
1	7W-0205	CORE GP/ TRANS OIL	1,611.17	1,611.17T
	LABOR	RECONDITION ONE 3406 CYLINDER BLOCK	1,800.00	1,800.00

Quote Approved by:

Subtotal

NOTE: Quote does not include any salvage or reconditioning machine work, any unforeseen, unacceptable Core Charges or Freight Charges. Quote does not include any REMOVAL or INSTALLATION CHARGES unless specified. Warranty is as follows: Twelve (12) months Parts & Workmanship. If a Warranty issue occurs, the Customer's Service records will be requested for inspection. ALL COMPONENTS ARE DYNO TESTED TO ENSURE THE QUALITY OF THE COMPONENT BEFORE BEING RELEASED TO THE CUSTOMER.

Sales Tax (8.75%)**Total**

BLANE'S EQUIPMENT REPAIR, INC.

8637 Hemlock Avenue, Fontana, CA 92335

Remit To: 34924 BORCHARD ROAD

LAKE ELSINORE, CA 92530

Phone#909-357-8391 Fax#909-829-8525

Amended Quote

Date	Quote #
8/11/2011	881-E3

CITY OF REDLANDS
PO BOX 3005
REDLANDS, CA 92373

		Description	Job #	Eq. or Serial #
		826-C ENGINE	11064	87X550
Qty	Part #	Description	Unit price	Total
	LABOR	CRANKSHAFT WOULD NOT POLISH, IT HAD TO BE CUT TO .025.025	800.00	800.00
	LABOR	AFTER COOLER UPDATE (Discounted invoice \$2,500.00 as per conversation with Fred on 9/8/2011)	0.00	0.00
Quote Approved by:			Subtotal	\$33,044.71
NOTE: Quote does not include any salvage or reconditioning machine work, any unforeseen, unacceptable Core Charges or Freight Charges. Quote does not include any REMOVAL or INSTALLATION CHARGES unless specified. Warranty is as follows: Twelve (12) months Parts & Workmanship. If a Warranty issue occurs, the Customer's Service records will be requested for inspection. ALL COMPONENTS ARE DYNO TESTED TO ENSURE THE QUALITY OF THE COMPONENT BEFORE BEING RELEASED TO THE CUSTOMER.			Sales Tax (8.75%)	\$1,689.07
			Total	\$34,733.78

BLANE'S EQUIPMENT REPAIR, INC.**Quote**

34924 BORCHARD RD. (Billing Address)
 LAKE ELSINORE, CA 92530
 Phone#909-357-8391 Fax#909-829-8525
 Shop: 8637 Hemlock Ave., Fontana 92336

Date	Quote #
4/20/2011	881-RJ2

CITY OF REDLANDS
 PO BOX 3005
 REDLANDS, CA 92373

Description			Job #	Eq. or Serial #
R & I COMP & CENTER PINS			11064	
Qty	Part #	Description	Unit price	Total
1	1W-0613	INDICATOR AIR FILLER RESTRICTION	42.33	42.33T
1	3B-7264	FITTING	5.79	5.79T
1	5P-4400	CONNECTOR	7.59	7.59T
1	8M-2771	CLIP	2.59	2.59T
3	5P-6011	TUBE	6.09	18.27T
1	5P-4423	ELBOW	5.03	5.03T
1	9S-8032	HOSE- DUST EJECTOR	7.17	7.17T
2	5P-0597	HOSE CLAMP	5.17	10.34T
1	8S-5444	CLAMP	32.51	32.51T
1	0L-2070	BOLT	0.79	0.79T
1	9S-8752	NUT	0.22	0.22T
1	7N-1760	EJECTOR/ EXH. STACK	256.86	256.86T
1	7N-1393	MUFFLER	653.24	653.24T
1	6I-0274	AIR FILTER (OUTER)	54.95	54.95T
1	6I-0273	AIR FILTER (INNER)	61.89	61.89T
2	1P-6832/114-3540	GASKET	15.96	31.92T
1	6F-8814	CLAMP	15.76	15.76T
1	1D-4717/6V-8801	NUT	0.25	0.25T
1	0S-1590	BOLT	0.71	0.71T
12	4L-6454	BOLT	0.37	4.44T
24	5P-1075	WASHER	0.56	13.44T
1	2M-1395	GASKET RAD	2.16	2.16T
30	5P-1262	CM HOSE- UPPER RADIATOR	1.30	39.00T
6	5P-0598	HOSE CLAMP	5.72	34.32T
40	5P-1265	CM HOSE LOWER RAD	1.58	63.20T
1	4N-1419	GASKET LOWER RAD	2.97	2.97T
1	4N-5396	HOSE AS.	55.26	55.26T
1	9M-3116	GASKET	3.59	3.59T
1	6B-4312	CLIP	33.42	33.42T
1	0S-1590	BOLT	0.71	0.71T
1	6V-8801	NUT	0.25	0.25T
2	8T-4896	WASHER	0.35	0.70T
4	7N-3674	BLOCK- RAD MOUNT	25.68	102.72T
4	7X-0325	BOLT	1.51	6.04T
12	8T-4223	WASHER	0.58	6.96T

Quote Approved by:

Subtotal

NOTE: Quote does not include any salvage or reconditioning machine work, any unforeseen, unacceptable Core Charges or Freight Charges. Quote does not include any REMOVAL or INSTALLATION CHARGES unless specified. Warranty is as follows: Twelve (12) months Parts & Workmanship unless otherwise stated on Quote or Invoice. If a Warranty issue occurs, the Customer's Service records will be requested for inspection. ALL COMPONENTS ARE DYNO TESTED TO ENSURE THE QUALITY OF THE COMPONENT BEFORE BEING RELEASED TO THE CUSTOMER.

Sales Tax (8.75%)**Total**

21,352.45

BLANE'S EQUIPMENT REPAIR, INC.

34924 BORCHARD RD. (Billing Address)
LAKE ELSINORE, CA 92530
Phone#909-357-8391 Fax#909-829-8525
Shop: 8637 Hemlock Ave., Fontana 92336

Quote

Date	Quote #
4/20/2011	881-R12

CITY OF REDLANDS
PO BOX 3005
REDLANDS, CA 92373

Description			Job #	Eq. or Serial #
R & I COMP & CENTER PINS			11064	
Qty	Part #	Description	Unit price	Total
4	8T-7008	BOLT		
19	8T-4896	WASHER	1.05	4.20T
4	8T-8917	BOLT	0.35	6.65T
40	5P-1075	WASHER	0.83	3.32T
26	0S-0509	BOLT	0.56	22.40T
4	7K-6058	BOLT	0.26	6.76T
4	7X-0622	WASHER	10.87	43.48T
14	0S-1594	BOLT	0.83	3.32T
1	5T-9136	HOSE AS. HIGH SPEED OIL CHANGE	0.35	4.90T
1	3V-3633	HOSE GREASE FAN DRIVE	39.95	39.95T
1	2V-8555	HOSE GREASE FAN DRIVE	18.51	18.51T
3	5B-0935	FITTING GREASE	15.08	15.08T
4	1A-8537	BOLT	2.11	6.33T
1	9M-8406	CLIP	2.91	11.64T
3	8M-2772	CLIP	4.49	4.49T
4	5P-8247	WASHER	3.32	9.96T
1	8H-2807	WASHER	0.99	3.96T
1	7E-5346	VALVE	18.09	18.09T
1	8H-2778	SEAL RING FUEL SCREEN	3.06	3.06T
1	6W-6840	HOSE AS. FUEL	3.27	3.27T
1	6W-6856	HOSE AS FUEL	37.01	37.01T
3	8M-2773	CLIP	43.46	43.46T
1	8R-8559	HOSE AS.	6.14	18.42T
1	8R-8560	HOSE AS.	57.69	57.69T
1	8S-8820	CLIP SHORT	56.86	56.86T
1	5M-1193	CLIP LONG	4.31	4.31T
1	6N-5926	SENDING UNIT TORQUE TEMP	41.93	41.93T
1	203-3221	SENDING UNIT TORQUE TEMP (EMS)	32.28	32.28T
			61.57	61.57T
250	5P-0767	CM HEATER HOSE		
250	5P-0765	CM HEATER HOSE	0.17	42.50T
4	5D-1026	CLAMP	0.17	42.50T
1	8B-8679	SPACER	1.98	7.92T
3	6D-1641	CLIP	6.32	6.32T
1	2P-8977	PLATE	6.41	19.23T
			14.28	14.28T

Quote Approved by:

Subtotal

Sales Tax (8.75%)

Total

NOTE: Quote does not include any salvage or reconditioning machine work, any unforeseen, unacceptable Core Charges or Freight Charges. Quote does not include any REMOVAL or INSTALLATION CHARGES unless specified. Warranty is as follows: Twelve (12) months Parts & Workmanship unless otherwise stated on Quote or Invoice. If a Warranty issue occurs, the Customer's Service records will be requested for inspection. ALL COMPONENTS ARE DYNO TESTED TO ENSURE THE QUALITY OF THE COMPONENT BEFORE BEING RELEASED TO THE CUSTOMER.

BLANE'S EQUIPMENT REPAIR, INC.

34924 BORCHARD RD. (Billing Address)
LAKE ELSINORE, CA 92530
Phone#909-357-8391 Fax#909-829-8525
Shop: 8637 Hemlock Ave., Fontana 92336

Quote

Date	Quote #
4/20/2011	881-R12

CITY OF REDLANDS
PO BOX 3005
REDLANDS, CA 92373

Description			Job #	Eq. or Serial #
R & I COMP & CENTER PINS			11084	
Qty	Part #	Description	Unit price	Total
1	6V-3886	VALVE- SHUTOFF		
1	8F-8151	VALVE- SHUTOFF	38.87	38.87T
			15.84	15.84T
1	1B-3057	CLIP		0.00
1	8M-2770	CLIP	5.52	5.52T
1	8R-3600	ANGLE	3.96	3.96T
2	5S-7379	BOLT	9.33	9.33T
2	6V-8801	NUT	0.35	0.70T
6	8T-4896	WASHER	0.25	0.50T
1	9M-9740/1R-0719	FILTER TRANSMISSION	0.35	2.10T
1	3D-2824	SEAL O RING	17.88	17.88T
1	2S-8439	SEAL O RING	1.52	1.52T
2	3J-1907	SEAL O RING	6.20	6.20T
1	5F-0149	SEAL	0.96	1.92T
1	2H-2665	SEAL O RING	5.47	5.47T
1	4S-8598	SCREEN	4.88	4.88T
1	4S-8603/240-8259	SCREEN/ MAG NET	14.61	14.61T
6	9V-7710	SPIDER AND BRG GP	64.06	64.06T
24	9V-3811	BOLT	155.49	932.94T
12	0L-1732	BOLT	12.90	309.60T
12	6B-6684	BOLT	1.87	22.44T
12	3H-7654	WASHER	0.50	6.00T
1	9V-1814	SEAL	0.50	6.00T
1	3B-8489	FITTING GREASE	22.06	22.06T
1	4B-4550/6U-1989	FITTING PRESSURE RELIEF	1.35	1.35T
8	9V-4319	BOLT	1.49	1.49T
8	3H-7654	WASHER	15.98	127.84T
8	6B-6684	NUT	0.50	4.00T
			0.50	4.00T
2	6N-1572	MOUNT AS. TRANSMISSION		
1	7N-4242	MOUNT AS. TRANSMISSION	165.86	331.72T
14	8T-8924	BOLT	659.57	659.57T
14	8T-4994	WASHER	3.55	49.70T
			1.17	16.38T
		NEUTRALIZER GP		
Quote Approved by:			Subtotal	
NOTE: Quote does not include any salvage or reconditioning machine work, any unforeseen, unacceptable Core Charges or Freight Charges. Quote does not include any REMOVAL or INSTALLATION CHARGES unless specified. Warranty is as follows: Twelve (12) months Parts & Workmanship unless otherwise stated on Quote or Invoice. If a Warranty issue occurs, the Customer's Service records will be requested for inspection. ALL COMPONENTS ARE DYNO TESTED TO ENSURE THE QUALITY OF THE COMPONENT BEFORE BEING RELEASED TO THE CUSTOMER.			Sales Tax (8.75%)	
			Total	

BLANE'S EQUIPMENT REPAIR, INC.

34924 BORCHARD RD. (Billing Address)

LAKE ELSINORE, CA 92530

Phone#909-357-8391 Fax#909-829-8525

Shop: 8637 Hemlock Ave., Fontana 92336

Quote

Date	Quote #
4/20/2011	881-R12

CITY OF REDLANDS

PO BOX 3005

REDLANDS, CA 92373

Description			Job #	Eq. or Serial #
R & I COMP & CENTER PINS			11064	
Qty	Part #	Description	Unit price	Total
1	6F-0711	SEAL O RING		
5	5H-9241	SCREW	2.49	2.49T
5	1H-4393	LOCKWASHER	1.54	7.70T
1	5P-9040	SEAL RING	0.50	2.50T
1	5V-6294	HARNESS AS.	2.97	2.97T
4	5S-7347	SCREW	24.01	24.01T
4	6D-3982	NUT	0.58	2.32T
2	9N-1750	SWITCH	1.47	5.88T
3	5S-4246	LOCKWASHER	16.34	32.68T
6	6V-8818	SCREW	0.17	0.51T
3	5S-4246	LOCKWASHER	0.58	3.48T
2	5V-1063	INSULATION	0.17	0.51T
1	4V-8819	GASKET	3.02	6.04T
1	9V-6375	SEAL	4.44	4.44T
1	5P-8907	SEAL O RING	9.04	9.04T
1	5P-4932	SEAL O RING	3.65	3.65T
4	5P-9592	WASHER	3.09	3.09T
			3.42	13.68T
POWER TRAIN HOSES AND SEALS				
1	7L-6326	CLIP		
1	7V-5242	HOSE AS.	7.86	7.86T
1	2V-6170	HOSE AS.	61.08	61.08T
4	4J-0522	SEAL O RING	126.61	126.61T
1	2V-6925	HOSE AS.	2.43	9.72T
10	5P-8244	WASHER	138.28	138.28T
10	0T-0772	BOLT	0.47	4.70T
2	1P-3705	SEAL O RING	0.71	7.10T
1	2V-4990	HOSE AS.	3.48	6.96T
4	1P-3709	SEAL- RECTANGULAR	115.32	115.32T
20	5P-1291	CM HOSE STK	4.23	16.92T
2	5P-0597	CLAMP	1.28	25.60T
1	4E-5250	HOSE- SUCTION	5.27	10.54T
1	9B-7237	BOLT	538.12	538.12T
2	8T-4896	WASHER	0.53	0.53T
1	6V-1572	CLIP	0.35	0.70T
			15.81	15.81T
Quote Approved by:			Subtotal	
NOTE: Quote does not include any salvage or reconditioning machine work, any unforeseen, unacceptable Core Charges or Freight Charges. Quote does not include any REMOVAL or INSTALLATION CHARGES unless specified. Warranty is as follows: Twelve (12) months Parts & Workmanship unless otherwise stated on Quote or Invoice. If a Warranty issue occurs, the Customer's Service records will be requested for inspection. ALL COMPONENTS ARE DYNO TESTED TO ENSURE THE QUALITY OF THE COMPONENT BEFORE BEING RELEASED TO THE CUSTOMER.			Sales Tax (8.75%)	
			Total	

BLANE'S EQUIPMENT REPAIR, INC.

34924 BORCHARD RD. (Billing Address)
 LAKE ELSINORE, CA 92530
 Phone#909-357-8391 Fax#909-829-8525
 Shop: 8637 Hemlock Ave., Fontana 92336

Quote

Date	Quote #
4/20/2011	881-RI2

CITY OF REDLANDS
 PO BOX 3005
 REDLANDS, CA 92373

Description			Job #	Eq. or Serial #
R & I COMP & CENTER PINS			11064	
Qty	Part #	Description	Unit price	Total
1	6V-1573	CLIP		
1	6V-8801	NUT	12.90	12.90T
1	0S-1587	BOLT	0.25	0.25T
2	5P-8245	WASHER	1.02	1.02T
1	4E-5251	BRACKET	0.64	1.28T
8	8T-8916	BOLT	26.01	26.01T
8	8T-4223	WASHER	0.77	6.16T
4	1P-4582	FLANGE HALF	0.58	4.64T
2	4J-0527	SEAL O RING	15.11	60.44T
1	10R-0400	STARTER MOTOR GP	3.22	6.44T
18	8T-9382	BOLT TRANSMISSION MOUNTING	605.26	605.26T
18	8T-5360	WASHER- TRANSMISSION MOUNTING	0.63	11.34T
4	0T-0768	BOLT	0.33	5.94T
1	5K-8385	SEAL LIP TYPE	0.81	3.24T
1	7K-0432	RING- RETAINING	24.29	24.29T
30	248-7521	GAL 30 WT. HYD OIL	6.73	6.73T
18	248-7521	GAL 30 WT. POWER TRAIN OIL	19.84	595.20T
25	238-8648	EXT. LIFE COOLANT	19.84	357.12T
			16.14	403.50T
	LABOR	R&I ENGINE AND TRANSMISSION	5,100.00	5,100.00
	LABOR	SEPARATE MACHINE. WELD UP WORN CENTER PIN BORES. LINE BORE TOP AND BOTTOM HOLE. INSTALL NEW BEARINGS AND COLLARS. RE-ALIGN FRONT AND REAR SECTION OF MACHINE. INSTALL PINS AND RETAINERS. GREASE.	7,200.00	7,200.00
Quote Approved by:			Subtotal	\$20,624.09
NOTE: Quote does not include any salvage or reconditioning machine work, any unforeseen, unacceptable Core Charges or Freight Charges. Quote does not include any REMOVAL or INSTALLATION CHARGES unless specified. Warranty is as follows: Twelve (12) months Parts & Workmanship unless otherwise stated on Quote or Invoice. If a Warranty issue occurs, the Customer's Service records will be requested for inspection. ALL COMPONENTS ARE DYNO TESTED TO ENSURE THE QUALITY OF THE COMPONENT BEFORE BEING RELEASED TO THE CUSTOMER.			Sales Tax (8.75%)	\$728.36
			Total	\$21,352.45

BLANE'S EQUIPMENT REPAIR, INC.

34924 BORCHARD RD. (Billing Address)
 LAKE ELSINORE, CA 92530
 Phone#909-357-8391 Fax#909-829-8525
 Shop: 8637 Hemlock Ave., Fontana 92336

Quote

Date	Quote #
8/11/2011	881-T-2

CITY OF REDLANDS
 PO BOX 3005
 REDLANDS, CA 92373

Description			Job #	Eq. or Serial #
826-C TRANS & DROP BOX				87X550
Qty	Part #	Description	Unit price	Total
1	161-9089/243-0728	TRANSMISSION	998.16	998.16T
1	5P-0403	DIRECT OVERHAUL GASKET KIT	21.24	21.24T
2	6Y-0296/106-7798	BEARING ROLLER	46.61	93.22T
1	6P-7705	BALL BEARING	193.03	193.03T
8	7G-0894/8E-8304	CARRIER	6.33	50.64T
8	5M-2054	THRUST WASHER	11.18	89.44T
3	4S-8546/6Y-3484	BEARING ROLLER ASSEMBLY	165.89	497.67T
2	9G-2991	BALL BEARING	55.03	110.06T
3	5M-6126	VESEBEL RING	14.56	43.68T
6	5M-7925	BEARING ROLLER ASSEMBLY	28.95	173.70T
12	7G-0897/282-5042	BEARING ROLLER ASSEMBLY	18.49	221.88T
3	1P-3958	THRUST WASHER	31.19	93.57T
14	3S-2708	BEARING ROLLER ASSEMBLY	4.54	63.56T
1	9F-3788	PIN	9.66	9.66T
1	6F-0156	SEAL - METAL	11.31	11.31T
6	8E-8316	SEAL - METAL	8.68	52.08T
1	9W-9831/238-5507	WASHER	15.05	15.05T
1	9U-7725	ORIFICE	42.30	42.30T
		GAL CAT YELLOW PAINT		
1	2H-6489	DROP BOX	56.20	56.20T
1	2H-6490	RACE	88.78	88.78T
4	1P-7834	RACE & ROLLER ASSEMBLY	45.43	181.72T
4	1P-7835	CUP	74.20	296.80T
2	6D-7690	CONE	27.49	54.98T
2	5P-3723	CUP	55.26	110.52T
1	3P-3503	CONE	55.85	55.85T
1	3P-2922	SHIM PACK	72.29	72.29T
2	2D-9457	SHIM PACK	115.09	230.18T
2	4F-2041	CONE	62.75	125.50T
1	5F-0149	CUP	4.98	4.98T
		SEAL		
Quote Approved by:			Subtotal	
NOTE: Quote does not include any salvage or reconditioning machine work, any unforeseen, unacceptable Core Charges or Freight Charges. Quote does not include any REMOVAL or INSTALLATION CHARGES unless specified. Warranty is as follows: Twelve (12) months Parts & Workmanship unless otherwise stated on Quote or Invoice. If a Warranty issue occurs, the Customer's Service records will be requested for inspection. ALL COMPONENTS ARE DYNO TESTED TO ENSURE THE QUALITY OF THE COMPONENT BEFORE BEING RELEASED TO THE CUSTOMER.			Sales Tax (8.75%)	
			Total	

21,177.85

BLANE'S EQUIPMENT REPAIR, INC.

34924 BORCHARD RD. (Billing Address)
 LAKE ELSINORE, CA 92530
 Phone#909-357-8391 Fax#909-829-8525
 Shop: 8637 Hemlock Ave., Fontana 92336

Quote

Date	Quote #
8/11/2011	881-T-2

CITY OF REDLANDS
 PO BOX 3005
 REDLANDS, CA 92373

Description			Job #	Eq. or Serial #
826-C TRANS & DROP BOX				87X550
Qty	Part #	Description	Unit price	Total
1	7K-5449	TORQUE CONVERTER		
1	7K-5448	CONE	19.88	19.88T
1	6P-7767	CUP	12.55	12.55T
1	2S-0679	SHIM PACK	94.62	94.62T
1	8M-0903	BEARING ASSEMBLY	166.76	166.76T
1	7J-8894	RING	16.93	16.93T
1	7J-8893	CUP	16.70	16.70T
1	1T-0577	CONE	26.31	26.31T
2	9S-5279	BEARING SLEEVE	25.77	51.54T
1	5P-3867	BEARING RACE & ROLLER ASSEMBLY	101.39	101.39T
1	1T-1534	RACE	70.90	70.90T
2	1T-0651	CARRIER	132.68	132.68T
1	1T-0762	RING	8.37	16.74T
1	1T-1078	RACE - SMALL FLAT	35.49	35.49T
4	1T-0686	BEARING - SMALL FLAT	30.94	30.94T
2	1T-0655	RACE - LARGE FLAT	42.40	169.60T
1	1T-0763	BEARING - LARGE FLAT	106.42	212.84T
		RACE - SMALL FLAT	8.72	8.72T
	LABOR	RECONDITION AND DYNO TEST (1) 826-C TRANSMISSION AND DROP BOX	2,496.00	2,496.00
		AMENDMENTS AFTER DISASSEMBLY AND INSPECTION		
1	3P-3060	SUN GEAR 1ST GEAR	323.73	323.73T
1	7G-0283	RING GEAR 1ST GEAR	556.30	556.30T
4	7G-2486	PLANETARY GEARS 1ST GEAR	151.92	607.68T
4	9G-5287	CLUTCH DISC (RUBBER STYLE)	217.27	869.08T
5	3P-7447	CLUTCH PLATE (LARGE)	286.90	1,434.50T
5	9P-6082	CLUTCH DISCS 2ND GEAR	130.42	652.10T
4	3P-7489	CLUTCH PLATE 2ND GEAR	66.82	267.28T
1	6P-7705	VESEBEL RING CARRIER	193.03	193.03T
36	1T-0689	TORQUE LID FLAT WASHER	0.39	14.04T
Quote Approved by:			Subtotal	
NOTE: Quote does not include any salvage or reconditioning machine work, any unforeseen, unacceptable Core Charges or Freight Charges. Quote does not include any REMOVAL or INSTALLATION CHARGES unless specified. Warranty is as follows: Twelve (12) months Parts & Workmanship unless otherwise stated on Quote or Invoice. If a Warranty issue occurs, the Customer's Service records will be requested for inspection. ALL COMPONENTS ARE DYNO TESTED TO ENSURE THE QUALITY OF THE COMPONENT BEFORE BEING RELEASED TO THE CUSTOMER.			Sales Tax (8.75%)	
			Total	

BLANE'S EQUIPMENT REPAIR, INC.

34924 BORCHARD RD. (Billing Address)
 LAKE ELSINORE, CA 92530
 Phone#909-357-8391 Fax#909-829-8525
 Shop: 8637 Hemlock Ave., Fontana 92336

Quote

Date	Quote #
8/11/2011	881-T-2

CITY OF REDLANDS
 PO BOX 3005
 REDLANDS, CA 92373

Description			Job #	Eq. or Serial #
826-C TRANS & DROP BOX				87X550
Qty	Part #	Description	Unit price	Total
1	1T-1340	HUB (TURBINE)	457.67	457.67T
1	1T-0649	SNAP RING (TORQUE CONVERTER)	6.28	6.28T
1	1T-1534	V-RING CARRIER (TORQUE CONVERTER)	132.68	132.68T
1	3P-3737	SEPARATOR PLATE - FORWARD & REVERSE	433.70	433.70T
1	1T-0665	RETAINER (TURBINE)	274.64	274.64T
1	3P-3418	REVERSE RING GEAR	475.86	475.86T
4	3P-3242	PLANET SHAFTS	61.71	246.84T
1	6V-1898	SNAP RING	4.19	4.19T
1	1T-0901	IMPELLER Used	574.19	574.19T
1	1T-1338	TORQUE OUTPUT DRIVE GEAR	393.92	393.92T
1	1T-0708	STATOR Used	494.00	494.00T
	LABOR	SLEEVE VESEBEL RING SEAL AREA ON 3RD TO 4TH GEAR SEPARATOR CLUTCH HOUSING	800.00	800.00
	LABOR	SLEEVE SEAL AREA ON TORQUE CONVERTER DRIVE FLANGE	458.04	458.04
	LABOR	REPAIR REACTION PIN DOWEL SLOTS ON FORWARD PISTON	300.00	300.00
		TRANSMISSION PUMP		
4	5M-3320	BEARING	23.22	92.88T
1	5S-6622	SEAL- LIP TYPE	8.44	8.44T
2	2D-8009	O-RING	5.06	10.12T
1	5F-3106	MOUNTING O-RING	4.89	4.89T
1	1S-2174	SEAL-O-RING	6.57	6.57T
1	3J-7354	SEAL-O-RING	0.76	0.76T
		PARKING BRAKE		
1	8H-8257	MOUNTING O-RING	10.44	10.44T
1	3K-2518	BALL BEARING	54.56	54.56T
1	3B-9378	LIP SEAL	23.42	23.42T
1	2H-2665	SEAL-O-RING	4.44	4.44T
Quote Approved by:			Subtotal	
NOTE: Quote does not include any salvage or reconditioning machine work, any unforeseen, unacceptable Core Charges or Freight Charges. Quote does not include any REMOVAL or INSTALLATION CHARGES unless specified. Warranty is as follows: Twelve (12) months Parts & Workmanship unless otherwise stated on Quote or Invoice. If a Warranty issue occurs, the Customer's Service records will be requested for inspection. ALL COMPONENTS ARE DYNO TESTED TO ENSURE THE QUALITY OF THE COMPONENT BEFORE BEING RELEASED TO THE CUSTOMER			Sales Tax (8.75%)	
			Total	

BLANE'S EQUIPMENT REPAIR, INC.

34924 BORCHARD RD. (Billing Address)
 LAKE ELSINORE, CA 92530
 Phone#909-357-8391 Fax#909-829-8525
 Shop: 8637 Hemlock Ave., Fontana 92336

Quote

Date	Quote #
8/11/2011	881-T-2

CITY OF REDLANDS
 PO BOX 3005
 REDLANDS, CA 92373

Description			Job #	Eq. or Serial #
826-C TRANS & DROP BOX				87X550
Qty	Part #	Description	Unit price	Total
1	5P-6686	PISTON SEAL INNER	10.99	10.99T
1	5P-6687	PISTON SEAL OUTER	12.71	12.71T
3	1V-8280	PLATE	141.03	423.09T
7	1V-8279	DISC ASSEMBLY	164.10	1,148.70T
1	3K-6905	VALVE	1.97	1.97T
1	3V-7065	PLATE (BASE)	266.57	266.57T
21	8T-4223	1/2 INCH FLAT WASHER	0.53	11.13T
Quote Approved by:			Subtotal	\$19,800.07
NOTE: Quote does not include any salvage or reconditioning machine work, any unforeseen, unacceptable Core Charges or Freight Charges. Quote does not include any REMOVAL or INSTALLATION CHARGES unless specified. Warranty is as follows: Twelve (12) months Parts & Workmanship unless otherwise stated on Quote or Invoice. If a Warranty issue occurs, the Customer's Service records will be requested for inspection. ALL COMPONENTS ARE DYNO TESTED TO ENSURE THE QUALITY OF THE COMPONENT BEFORE BEING RELEASED TO THE CUSTOMER.			Sales Tax (8.75%)	\$1,377.78
			Total	\$21,177.85

BLANE'S EQUIPMENT REPAIR, INC.

34924 BORCHARD RD. (Billing Address)
LAKE ELSINORE, CA 92530
Phone#909-357-8391 Fax#909-829-8525
Shop: 8637 Hemlock Ave., Fontana 92336

Quote

Date	Quote #
5/16/2011	919

CITY OF REDLANDS
PO BOX 3005
REDLANDS, CA 92373

Description			Job #	Eq. or Serial #
826-C F. DIFF			11064	
Qty	Part #	Description	Unit price	Total
		PARTS NEEDED TO RECONDITION ONE 826-C FRONT DIFFERENTIAL/ WHEEL AND BRAKE GROUPS ASSEMBLY (WORST CASE)	13,000.00	13,000.00
	LABOR	RECONDITION ONE 826-C FRONT DIFFERENTIAL/ WHEEL AND BRAKE GROUPS ASSEMBLY	3,060.00	3,060.00
	LABOR	REMOVE AND REINSTALL ONE 826-C FRONT DIFFERENTIAL/ WHEEL AND BRAKE GROUPS ASSEMBLY	2,750.00	2,750.00
Quote Approved by:			Subtotal	\$18,810.00
NOTE: Quote does not include any salvage or reconditioning machine work, any unforeseen, unacceptable Core Charges or Freight Charges. Quote does not include any REMOVAL or INSTALLATION CHARGES unless specified. Warranty is as follows: Twelve (12) months Parts & Workmanship unless otherwise stated on Quote or Invoice. If a Warranty issue occurs, the Customer's Service records will be requested for inspection. ALL COMPONENTS ARE DYNO TESTED TO ENSURE THE QUALITY OF THE COMPONENT BEFORE BEING RELEASED TO THE CUSTOMER.			Sales Tax (8.75%)	\$1,137.50
			Total	\$19,947.50

BLANE'S EQUIPMENT REPAIR, INC.

34924 BORCHARD RD. (Billing Address)
 LAKE ELSINORE, CA 92530
 Phone#909-357-8391 Fax#909-829-8525
 Shop: 8637 Hemlock Ave., Fontana 92336

CITY OF REDLANDS
 PO BOX 3005
 REDLANDS, CA 92373

Quote

Date	Quote #
4/25/2011	909

Description			Job #	Eq. or Serial #
HYD PUMP			11064	
Qty	Part #	Description	Unit price	Total
1	0R-1456	CARTRIDGE GP 42 GPM	621.06	621.06T
1	0R-1469	CARTRIDGE GP 30 GPM	452.44	452.44T
1	8J-6887	SHAFT	196.86	196.86T
1	5P-0904	SEAL LIP	22.42	22.42T
1	6V-2318	SEAL LIP	19.75	19.75T
1	3L-1425	BALL BEARING	40.02	40.02T
1	3J-7719	RING RETAINING	4.70	4.70T
1	4C-4200	CAT YELLOW PAINT	9.06	9.06T
1	6V-0185	SURFACE DISC	4.54	4.54T
	LABOR	RECONDITION ONE 826-C HYD PUMP	255.00	255.00

Quote Approved by:

Subtotal \$1,625.85

NOTE: Quote does not include any salvage or reconditioning machine work, any unforeseen, unacceptable Core Charges or Freight Charges. Quote does not include any REMOVAL or INSTALLATION CHARGES unless specified. Warranty is as follows: Twelve (12) months Parts & Workmanship unless otherwise stated on Quote or Invoice. If a Warranty issue occurs, the Customer's Service records will be requested for inspection. ALL COMPONENTS ARE DYNO TESTED TO ENSURE THE QUALITY OF THE COMPONENT BEFORE BEING RELEASED TO THE CUSTOMER.

Sales Tax (8.75%) \$119.95**Total** \$1,745.80